

# LB700 - Bug #717

thermal dmc cpufreq

12/16/2024 05:01 PM -

|                        |  |                        |  |
|------------------------|--|------------------------|--|
| <b>Status:</b>         | New  | <b>Start date:</b>     | 12/16/2024   |
| <b>Priority:</b>       | High   | <b>Due date:</b>       |  |
| <b>Assignee:</b>       | sun  | <b>% Done:</b>         | 0%   |
| <b>Category:</b>       | Driver   | <b>Estimated time:</b> | 0.00 hour  |
| <b>Target version:</b> |  | <b>Spent time:</b>     | 0.00 hour  |
| <b>ID:</b>             | LB700  | <b>OS:</b>             | Linux Hi3403 4.19.90 #5 SMP Wed Feb 12 14:45:29 CST 2025 aarch64 aarch64 aarch64 GNU/Linux |
| <b>CPU:</b>            | hisi3403   | <b>APP:</b>            | -  |
| <b>Model:</b>          |  | <b>Board:</b>          |  |
| <b>Part number:</b>    | 01   | <b>Board ID:</b>       | FD7352S  |
| <b>Part name:</b>      |  | <b>Board name:</b>     | YT8521SC   |
| <b>Image path:</b>     | \\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304 | <b>EMMC:</b>           | FORESEE(FSEIASLD-32G)  |
| <b>OS:</b>             | Ubuntu   |                        |  |

## Description

### History

#1 - 12/18/2024 05:45 PM - sun

1.hisi3403

#2 - 03/07/2025 02:44 PM -

changed from <https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian> to \\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu\_V1.3-support-UI-20250304

changed from Linux Hi3403 4.19.90 #3 SMP Sat Dec 7 17:52:22 CST 2024 aarch64 aarch64 aarch64 GNU/Linux to Linux Hi3403 4.19.90 #5 SMP Wed Feb 12 14:45:29 CST 2025 aarch64 aarch64 aarch64 GNU/Linux

ubuntu\_V1.3-support-UI-20250304 thermal dmc cpufreq