

LZ210 - Bug #750

WIFI/BT

12/24/2024 05:26 PM -

Status:	Closed	Start date:	12/24/2024
Priority:	Normal	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LZ210	OS:	Ubuntu
CPU:	RK3562	Kernel:	V6.1.84
GPU:	LCH3576	APP:	-
RAM/Flash:	-	Flash:	100%
Bootloader:	01	Bootloader:	N/S
Bootloader/Kernel:	01	Bootloader/Kernel:	YT8521SC
Kernel:	rk3562_lkd210_ubuntu22.04_12_13.img	EMMC:	-
Description			

History

#1 - 12/31/2024 02:16 PM - KuangJie

\\192.168.1.250\01-Public\rk3562\rk3562_lkd210_ubuntu22.04_12_29.img

#2 - 01/03/2025 06:15 PM -

- File clipboard-202501031813-cxd6a.png added
- File clipboard-202501031815-3afnw.png added
- Status changed from New to Closed

KuangJie wrote in [#note-1](#):

\\192.168.1.250\01-Public\rk3562\rk3562_lkd210_ubuntu22.04_12_29.img

```
root@RK3562:~# ifconfig
eth0: flags=4163<UP,BROADCAST,RUNNING,MULTICAST> mtu 1500
    ether 8e:16:f4:2c:5f:3f txqueuelen 1000 (Ethernet)
    RX packets 6094 bytes 1633557 (1.6 MB)
    RX errors 0 dropped 19 overruns 0 frame 0
    TX packets 191 bytes 35597 (35.5 KB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 40

lo: flags=73<UP,LOOPBACK,RUNNING> mtu 65536
    inet 127.0.0.1 netmask 255.0.0.0
    inet6 ::1 prefixlen 128 scopeid 0x10<host>
    loop txqueuelen 1000 (Local Loopback)
    RX packets 205 bytes 18217 (18.2 KB)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 205 bytes 18217 (18.2 KB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0

wlan0: flags=4163<UP,BROADCAST,RUNNING,MULTICAST> mtu 1500
    inet 192.168.31.150 netmask 255.255.255.0 broadcast 192.168.31.255
    inet6 fe80::b367:8ee4:d00b:373 prefixlen 64 scopeid 0x20<link>
    ether 24:ef:b4:51:ba:ab txqueuelen 1000 (Ethernet)
    RX packets 1120 bytes 403719 (403.7 KB)
    RX errors 0 dropped 39 overruns 0 frame 0
    TX packets 46 bytes 5450 (5.4 KB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0

root@RK3562:~# ping 192.168.31.150
PING 192.168.31.150 (192.168.31.150) 56(84) bytes of data.
64 bytes from 192.168.31.150: icmp_seq=1 ttl=64 time=0.169 ms
64 bytes from 192.168.31.150: icmp_seq=2 ttl=64 time=0.189 ms
64 bytes from 192.168.31.150: icmp_seq=3 ttl=64 time=0.174 ms
64 bytes from 192.168.31.150: icmp_seq=4 ttl=64 time=0.163 ms
64 bytes from 192.168.31.150: icmp_seq=5 ttl=64 time=0.164 ms
^C
--- 192.168.31.150 ping statistics ---
5 packets transmitted, 5 received, 0% packet loss, time 4094ms
rtt min/avg/max/mdev = 0.163/0.171/0.189/0.009 ms

root@RK3562:~# hciconfig -a
hci0: Type: Primary Bus: SDIO
      BD Address: 24:EF:B4:51:BA:AC ACL MTU: 1021:9 SCO MTU: 255:4
      UP RUNNING
      RX bytes:0 acl:0 sco:0 events:67 errors:0
      TX bytes:4164 acl:0 sco:0 commands:70 errors:0
      Features: 0xbf 0xee 0xd 0xfe 0xdb 0xfd 0x7b 0x87
      Packet type: DM1 DM3 DM5 DH1 DH3 DH5 HV1 HV3
      Link policy: RSWITCH SNIFF
      Link mode: PERIPHERAL ACCEPT
      Name: 'RK3562'
      Class: 0x6c0000
      Service Classes: Rendering, Capturing, Audio, Telephony
      Device Class: Miscellaneous,
      HCI Version: 5.0 (0x9) Revision: 0x17
      LMP Version: 5.0 (0x9) Subversion: 0x17
      Manufacturer: not assigned (3149)

root@RK3562:~# █
```

WIFI

BT

WIFI/BTXXXXXXXXXXXXBUG

Files

clipboard-202501031813-cxd6a.png	82.3 KB	01/03/2025	□□
clipboard-202501031815-3afnw.png	101 KB	01/03/2025	□□