

WiFi - Bug #756

FD7352S-BS STA 2.4G WiFi Rx

12/25/2024 02:08 PM - EGON

Status:	Closed	Start date:	12/25/2024
Priority:	Normal	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LZ160	OS:	Ubuntu
CPU:	RK3588	OS version:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
Model:	LKD3588	APP:	
Model/Version:		Model:	
Model/Version:	01	Model:	FD7352S
Model/Version:	03	Model:	
Model:	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	EMMC:	-

Description

FD7352S -BS STA 2.4G WiFi Rx

```
Connected to cc:29:bd:0c:0f:61 (on wlan0)
  SSID: ceshi
  freq: 2462
  RX: 0 bytes (0 packets)
  TX: 0 bytes (0 packets)
  signal: -32 dBm
  rx bitrate: 192.2 MBit/s VHT-MCS 9 short GI VHT-NSS 2
  tx bitrate: 144.4 MBit/s MCS 15 short GI
-----
Connected to cc:29:bd:0c:0f:61 (on wlan0)
  SSID: ceshi
  freq: 2462
  RX: 0 bytes (0 packets)
  TX: 0 bytes (0 packets)
  signal: -33 dBm
  rx bitrate: 192.2 MBit/s VHT-MCS 9 short GI VHT-NSS 2
  tx bitrate: 144.4 MBit/s MCS 15 short GI
-----
```

History

#1 - 12/27/2024 10:25 AM - EGON

- set to Ubuntu

#2 - 12/27/2024 10:26 AM - EGON

- Subject changed from STA 2.4G WiFi Rx to FD7352S-BS STA 2.4G WiFi Rx

#3 - 01/09/2025 01:42 PM - EGON
- Status changed from New to Closed

Files

□□□□□_17351067661626.png	22.7 KB	12/25/2024	EGON
--------------------------	---------	------------	------