

WIFI - Bug #759

FD7352S-BS wifi

12/25/2024 03:47 PM - EGON

Status:	Closed	Start date:	12/25/2024
Priority:	Normal	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LZ160	OS:	Ubuntu
CPU:	RK3588	Kernel:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
Model:	LKD3588	APP:	
Board:		Board:	
Board ID:	01	Board ID:	FD7352S
Board Name:	03	Board Name:	
Board Path:	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	EMMC:	-

Description

wifi

```
root@LPA3588:/home/neardi/Desktop# ls
cpu_set.sh FD7256forAP hostapd2.10 skw6316.ko skwbt.ko skw_sdio_v20.ko
root@LPA3588:/home/neardi/Desktop# insmod skw_sdio_v20.ko
[ 68.535238] [SKWSDIO INFO] skw_sdio_scan_card: sdio_scan_card
[ 68.535909] skw_sdio_probe: func->class=0, vendor=0x1ffe, device=0x6316, func_num=0x0001, clock=150000000 blksize=0x200 max_blkcnt 2048
[ 68.536129] [SKWSDIO INFO] skw_sdio_probe: sdio_enable_func ret=0 type 0
[ 68.561250] [SKWSDIO INFO] skw_sdio_probe: enable func1 done
```

History

#1 - 12/27/2024 10:24 AM - EGON

- Subject changed from wifi to FD7352S-BS wifi

#2 - 12/27/2024 05:29 PM - KuangJie

dtb

#3 - 12/27/2024 05:33 PM - EGON

- Status changed from New to Closed

Files

17351128009754.png	23.1 KB	12/25/2024	EGON
--------------------	---------	------------	------