

LP112 - Bug #776

USB2.0 USB1.0

01/02/2025 02:04 PM -

Status:	New	Start date:	01/02/2025
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP112	:	Ubuntu
CPU:	RK3399Pro	:	V4.4.194
:	LPB3399Pro	APP:	-
/:	-	:	100%
:	01	:	N/S
/:	01	:	N/S
:	LZ112_3588_ubuntu20.04_v1.0_20240204_1649	EMMC:	-

Description

1USB2.02.0SATA
2isusb -T | grep Mass ; lsblk
3logisusb -T | grep Mass ; lsblk
USB2.0USB1.0/1.0

```
root@LPA3399PR0:/media/neardi# mount /dev/sda1 /media/neardi/A/
root@LPA3399PR0:/media/neardi#
root@LPA3399PR0:/media/neardi#
root@LPA3399PR0:/media/neardi#
root@LPA3399PR0:/media/neardi# lsusb -t | grep Mass;lsblk
    __ Port 1: Dev 2, If 0, Class=Mass Storage, Driver=usb-storage, 12M
NAME      MAJ:MIN RM  SIZE RO TYPE MOUNTPOINT
sda             8:0    0  477G  0 disk
└─sda1          8:1    0  477G  0 part /media/neardi/A
mmcblk1       179:0    0   57.6G  0 disk
├─mmcblk1p1    179:1    0     4M  0 part
├─mmcblk1p2    179:2    0     4M  0 part
├─mmcblk1p3    179:3    0    32M  0 part
├─mmcblk1p4    179:4    0    96M  0 part
├─mmcblk1p5    179:5    0    32M  0 part
└─mmcblk1p6    179:6    0   51.4G  0 part /
mmcblk1boot0   179:32    0     4M  1 disk
mmcblk1boot1   179:64    0     4M  1 disk
mmcblk1rpm     179:96    0    16M  0 disk
root@LPA3399PR0:/media/neardi#
```

```

root@LPA3399PR0:~# lsusb -t | grep Mass:lsblk
    |__ Port 1: Dev 2, If 0, Class=Mass Storage, Driver=usb-storage, 480M USB2.0
NAME MAJ:MIN RM SIZE RO TYPE MOUNTPOINT
sda      8:0    0 477G 0 disk
├─sda1    8:1    0 477G 0 part /media/neardi/XXDATA 挂载成功
├─mmcblk1 179:0    0 57.6G 0 disk
├─mmcblk1p1 179:1    0 4M 0 part
├─mmcblk1p2 179:2    0 4M 0 part
├─mmcblk1p3 179:3    0 32M 0 part
├─mmcblk1p4 179:4    0 96M 0 part
├─mmcblk1p5 179:5    0 32M 0 part
├─mmcblk1p6 179:6    0 51.4G 0 part /
mmcblk1boot0 179:32    0 4M 1 disk
mmcblk1boot1 179:64    0 4M 1 disk
mmcblk1rmpb 179:96    0 16M 0 disk

root@LPA3399PR0:~# [ 64.308033] usb usb1-port1: Cannot enable. Maybe the USB cable is bad?
[ 65.163198] usb usb1-port1: Cannot enable. Maybe the USB cable is bad?
[ 66.019192] usb usb1-port1: Cannot enable. Maybe the USB cable is bad?
[ 66.875200] usb usb1-port1: Cannot enable. Maybe the USB cable is bad?
[ 66.884120] blk_update_request: I/O error, dev sda, sector 470814530
[ 66.884911] blk_update_request: I/O error, dev sda, sector 470814770
[ 66.885816] Aborting journal on device sda1-8.
[ 66.886251] JBD2: Error -5 detected when updating journal superblock for sda1-8.
[ 67.756004] usb usb1-port1: Cannot enable. Maybe the USB cable is bad?
[ 68.611194] usb usb1-port1: Cannot enable. Maybe the USB cable is bad?
[ 69.769198] usb usb1-port1: Cannot enable. Maybe the USB cable is bad?

lsusb -t | grep Mass:lsblk
    |__ Port 1: Dev 2, If 0, Class=Mass Storage, Driver=usb-storage, 12M USB1.0
NAME MAJ:MIN RM SIZE RO TYPE MOUNTPOINT
sda      8:0    0 477G 0 disk
├─sda1    8:1    0 477G 0 part 没有自动挂载
├─mmcblk1 179:0    0 57.6G 0 disk
├─mmcblk1p1 179:1    0 4M 0 part
├─mmcblk1p2 179:2    0 4M 0 part
├─mmcblk1p3 179:3    0 32M 0 part
├─mmcblk1p4 179:4    0 96M 0 part
├─mmcblk1p5 179:5    0 32M 0 part
├─mmcblk1p6 179:6    0 51.4G 0 part /
mmcblk1boot0 179:32    0 4M 1 disk
mmcblk1boot1 179:64    0 4M 1 disk
mmcblk1rmpb 179:96    0 16M 0 disk

```

拔出后USB识别成1.0

History

- File clipboard-202501021404-x9epj.png added

Files