

KP12C - Bug #791

TF

01/08/2025 08:08 PM - mike

Status:	New	Start date:	01/08/2025
Priority:	Urgent	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	KP12C	OS:	Ubuntu
CPU:	RK3568	Kernel:	Linux LPA3568 5.10.198 #13 SMP Mon Jan 6 18:37:40 CST 2025 aarch64 aarch64 GNU/Linux
Model:	"LPA3568M4"	APP:	-
Bootloader:	05	Flash:	100%
Partition:	04	Flash:	RTL8852
Bootloader:	04	Flash:	YT8521SC
Image:	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img	EMMC:	-

Description

```
root@LPA3568:~# dmesg
[ 334.024364] mmc_host mmc1: Bus speed (slot 0) = 375000Hz (slot req 400000Hz, actual 375000HZ div = 0)
[ 334.090743] mmc1: error -110 whilst initialising SD card
[ 334.103525] mmc_host mmc1: Bus speed (slot 0) = 375000Hz (slot req 375000Hz, actual 375000HZ div = 0)
root@LPA3568:~# lsblk
NAME        MAJ:MIN RM  SIZE RO TYPE MOUNTPOINT
sda           8:0    1   100M  0 disk /media/neardi/283A-CF0C
mmcblk0     179:0    0   28.9G  0 disk
├─mmcblk0p1  179:1    0     4M  0 part
├─mmcblk0p2  179:2    0     4M  0 part
├─mmcblk0p3  179:3    0    64M  0 part
├─mmcblk0p4  179:4    0   128M  0 part
├─mmcblk0p5  179:5    0    32M  0 part
└─mmcblk0p6  179:6    0   28.7G  0 part /
mmcblk0boot0 179:32    0     4M  1 disk
mmcblk0boot1 179:64    0     4M  1 disk
nvme0n1      259:0    0  119.2G  0 disk
root@LPA3568:~#
```

History

#1 - 01/10/2025 10:33 AM -

- File sd log.txt added
- File sd log.txt added

mmc log
40kHz 30kHz 20kHz 10kHz sd 20kHz CMD sd CMD

Files

clipboard-202501082004-lennx.png	24.7 KB	01/08/2025	mike
sd log.txt	6.62 KB	01/10/2025	
sd log.txt	117 KB	01/10/2025	