


LP201 - Bug #864

U9606/U9607/U9608

03/04/2025 06:08 PM - mike

Status:	New	Start date:	03/04/2025
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	M.E	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LP201	OS:	Ubuntu
CPU:	RK3576	Kernel:	V6.1.84
GPU:	LPS3576	APP:	-
RAM:	-	RAM:	100%
Storage:	-	Storage:	FD7256S
Power:	01	Power:	YT8521SC
Other:	-	EMMC:	-

Description



ABS 3mm U9606/U9607/U9608 3.1 4mm

Files

clipboard-202503041745-3oafw.png	217 KB	03/04/2025	mike
----------------------------------	--------	------------	------