

LP160 - Bug #886

HDMI

03/17/2025 09:47 AM - EGON

Status:	New	Start date:	03/17/2025
Priority:	High	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LZ160	OS:	Android
CPU:	RK3588	Compiler:	Linux version 5.10.66 (sundongya@ubuntu2204-docker) (Android (7284624, based on r416183b) clang version 12.0.5 (https://android.googlesource.com/toolchain/llvm-project c935d99d7cf2016289302412d708641d5 2d2f7ee), LLD 12.0.5 (/buildbot/src/android/llvm-toolchain/out/llvm-project/lld c935d99d7cf2016289302412d708641d5 2d2f7ee)) #23 SMP PREEMPT Sun Jan 12 18:14:48 CST 2025
Kernel:	LKD3588	APP:	
Kernel version:		Kernel version:	100%
Kernel version:	01	Kernel version:	
Kernel version:	03	Kernel version:	
Kernel version:	\\192.168.1.250\03-image\rk3588-a12\LKD3588-\\lkd3588-android12-V3-fd7352s-bt-ok-20250114\lkd3588-android12-V3-fd7352s-bt-ok-20250114.img	EMMC:	-
Description			
HDMI			