


LZ201 - Bug #968

WiFi network_timeout

06/05/2025 06:23 PM

Status:	New	Start date:	06/05/2025
Priority:	Normal	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LZ201	:	Ubuntu
CPU:	RK3576	:	Linux LB3576 6.1.84 #77 SMP Tue Apr 29 15:07:15 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
:	LPS3576	APP:	-
/:	02	:	100%
:	02	:	FD7352S
/:	-	:	N/A
:	rk3576_ubuntu2204_20250522.img	EMMC:	-

Description



Files

clipboard-202506051820-nxwux.png	86 KB	06/05/2025	
startup.xml	132 KB	06/05/2025	