

LB160 - Bug #983

5V0 3V3

06/19/2025 04:03 PM -

Status:	New	Start date:	06/19/2025
Priority:	High	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
 :		 :	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img
CPU:	RK3588	 :	Ubuntu
 :		 :	Linux LPA3588 6.1.99
 / :		 :	FD7352S
 :		 :	
 / :	01	EMMC :	-
Description			
5V0 3V3			