

DQA - Issues

#	Tracker	Status	Priority	Subject	OS	Details	Assignee	Updated
922	Bug	New	Normal	LP160 log	Ubuntu	03-image/rk3588-linux/LPA3588-/ipa3588_f0_ubuntu22.04_linux_6.1_fd7352s_ap6275s_v2.0_20250326	sun	04/03/2025 07:07 PM
921	Bug	New	Urgent	1000M	Ubuntu	fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	sun	04/03/2025 02:59 PM
920	Bug	New	High	audio demo	Ubuntu	fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	Linx	04/03/2025 02:57 PM
919	Bug	New	Urgent	gpio50	Ubuntu	fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	jing	04/03/2025 02:43 PM
918	Bug	New	Urgent	USB 100M ssh camera	Ubuntu	fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	sun	04/03/2025 02:28 PM
917	Bug	New	High	IP	Ubuntu	fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	Linx	04/02/2025 06:18 PM
916	Bug	New	High	IP	Ubuntu	192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	Linx	04/02/2025 06:16 PM
915	Bug	New	High	neardi		fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	sun	04/08/2025 06:20 PM
914	Bug	New	Urgent	Out of memory		fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	sun	04/08/2025 06:19 PM
913	Bug	New	High	J2600--normal		fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	sun	04/02/2025 05:29 PM
912	Bug	New	High	J2903--TP		fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	sun	04/02/2025 05:28 PM
911	Bug	New	High	J2904--30pin FPC		fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	sun	04/02/2025 05:25 PM
910	Bug	New	High		Ubuntu	fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	jing	04/02/2025 05:18 PM
909	Bug	New	Urgent	ddr	Ubuntu	fastboot kernel 192.168.1.250/03-image/hisi3402/imageOS/ubuntu/ubuntu_V1.0-20250225 rootfs 192.168.1.250/01-Public/Linx\hi3403/ubuntu/20250326	Linx	04/02/2025 05:38 PM
907	Bug	New	Urgent	usb3.0hub U	Ubuntu	192.168.1.250/01-Public/Linx\rk3562/20250321	Linx	04/01/2025 09:46 AM

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
905	Bug	New	Urgent	ddr	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/31/2025 05:50 PM
904	Bug	New	High	Neardi		\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:31 PM
903	Bug	New	Urgent		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10		03/31/2025 09:42 AM
902	Bug	New	High	camera	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:36 PM
901	Bug	New	High	USB100Msshcamera	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:33 PM
900	Bug	New	High	audiodemoaudio	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:30 PM
899	Bug	New	High	J2904--30pin FPC	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:57 PM
898	Bug	New	High	J2903--TP	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:46 PM
897	Bug	New	High	J2600--normal	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:42 PM
896	Bug	New	High	npu demoNPU	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:35 PM
895	Bug	New	Urgent	PCIEM.2	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
894	Bug	New	High		Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
893	Bug	New	Urgent	1000M	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
890	Bug	New	High	LED	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321		03/21/2025 06:54 PM
888	Bug	New	High	USB3.0HUBHUB	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321		03/21/2025 06:27 PM
887	Bug	New	High		Ubuntu	\\192.168.1.250\01-Public\rk3562\rk3562_lkd210_ubuntu22.04_12_29.img		03/20/2025 06:48 PM
886	Bug	New	High	HDMI	Android	\\192.168.1.250\03-image\rk3588-a12\LKD3588-\lkd3588-android12-V3-fd7352s-bt-ok-20250114\lkd3588-android12-V3-fd7352s-bt-ok-20250114.img	sun	03/17/2025 09:47 AM
885	Bug	New	Urgent	FD7352Swifi	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117		03/17/2025 09:40 AM
884	Bug	New	Urgent	can	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10		03/11/2025 04:22 PM
879	Bug	New	High	HDMI	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314	Linx	03/14/2025 03:26 PM
874	Bug	New	High	J2904--30pin FPC	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304		03/06/2025 03:19 PM
872	Bug	New	Normal	camera demo	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:37 PM
871	Bug	New	High	Neardi	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:23 PM
870	Bug	New	Urgent	ubuntusyncemmc	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025-01-23	Linx	03/05/2025 06:21 PM
868	Bug	New	High		Ubuntu	-		03/04/2025 07:46 PM

#	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
867	Bug	New	High	蓝牙鼠标	Ubuntu	-	liang	03/04/2025 07:44 PM
866	Bug	New	Urgent	TYPE-C/SIM 读卡器	Ubuntu	-	liang	03/04/2025 06:57 PM
865	Bug	New	High	蓝牙鼠标无法使用	Ubuntu	-	liang	03/04/2025 06:40 PM
864	Bug	New	High	U9606/U9607/U9608 蓝牙鼠标无法使用	Ubuntu	-	liang	03/04/2025 06:08 PM
863	Bug	New	High	M4 蓝牙鼠标无法使用	Ubuntu	-	liang	03/04/2025 05:21 PM
862	Bug	New	Normal	蓝牙鼠标无法使用	Ubuntu	-	liang	03/04/2025 04:38 PM
860	Bug	New	High	CR 读卡器无法使用	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/04/2025 03:09 PM
857	Bug	New	High	RTC 读卡器无法使用	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
855	Bug	New	High	蓝牙鼠标无法使用	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:14 PM
854	Bug	New	Normal	蓝牙鼠标无法使用	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	Linx	02/28/2025 02:23 PM
852	Bug	New	Urgent	type-c 读卡器无法使用		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img	liang	02/28/2025 11:25 AM
851	Bug	New	High	蓝牙鼠标无法使用 cat /dev/ttyS3 无法使用 BDGGA 无法使用 BDGSV	Ubuntu	ubuntu22.04_lb201_25_01_07.img	liang	02/27/2025 06:53 PM
850	Bug	New	High	MIC 无法使用 MIC 无法使用	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/28/2025 02:18 PM
849	Bug	New	High	蓝牙 MINI PCIE 读卡器无法使用 M.2 读卡器	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 05:15 PM
848	Bug	New	Urgent	蓝牙 PCIE 读卡器无法使用	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 04:25 PM
847	Bug	New	High	蓝牙鼠标无法使用 5G 蓝牙鼠标无法使用	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:17 PM
845	Bug	New	High	USB3.0 读卡器 HUB 无法使用 读卡器无法使用	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/27/2025 03:25 PM
844	Bug	New	High	audio 无法使用 demo 无法使用 audio 无法使用	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:38 PM
840	Bug	New	Normal	蓝牙 mmcb1ko 无法使用 mmcb1k1	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/18/2025 05:20 PM
837	Bug	New	Urgent	USB3.0 读卡器 3.0 读卡器无法使用		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	yuncai	02/18/2025 02:23 PM
836	Bug	New	Normal	蓝牙 无法使用 无法使用 无法使用		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/17/2025 03:31 PM
835	Bug	New	Normal	WiFi 无法使用 WiFi 无法使用				02/14/2025 04:11 PM
834	Bug	New	Normal	蓝牙 HDMI 无法使用 HDMI 无法使用 SPK 无法使用	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/14/2025 02:42 PM

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
802	Bug	New	Normal	WiFi连接不上				01/15/2025 03:28 PM
801	Bug	New	Urgent	WiFi连接不上				01/15/2025 03:26 PM
800	Bug	New	High	WiFi连接不上				02/06/2025 10:24 AM
799	Bug	New	Normal	WiFi连接不上				01/15/2025 03:18 PM
796	Bug	New	Normal	usb2.0 usb3.0 hub 30%延迟	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	Linx	01/14/2025 11:54 AM
795	Bug	New	Normal	AHD摄像头	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	王	01/13/2025 09:55 AM
793	Bug	New	Normal	FD7352S-BS AP连接不上		rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	01/09/2025 01:50 PM
792	Bug	New	High	LCD屏幕	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/09/2025 10:04 AM
791	Bug	New	Urgent	TF卡	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img	王	01/10/2025 10:33 AM
790	Bug	New	High	连接不上	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 08:02 PM
789	Bug	New	High	RS485/CAN接口	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 07:57 PM
787	Bug	New	Urgent	摄像头3-5帧	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/22/2025 10:42 AM
786	Bug	New	High	摄像头	Ubuntu		jing	01/08/2025 05:48 PM
785	Bug	New	Immediate	摄像头	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 06:19 PM
784	Bug	New	Urgent	FD7352S-BS For LKD3588 iperf3 -c udp iperf3 -s	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img		01/09/2025 03:37 PM
783	Bug	New	Urgent	FD7352S-BS STA AX80 udp连接不上	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	01/09/2025 01:43 PM
782	Bug	New	High	eth1接口	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	02/26/2025 03:49 PM
781	Bug	New	High	DC/IN接口	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 11:32 AM
780	Bug	New	Low	C2045 J9200接口	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/08/2025 10:47 AM
778	Bug	New	High	AHD摄像头	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img	王	01/06/2025 09:08 PM
776	Bug	New	High	USB2.0 USB1.0接口	Ubuntu	LZ112_3588_ubuntu20.04_v1.0_20240204_1649	王	01/02/2025 02:05 PM
775	Bug	New	Normal	ETH接口ifconfig	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	12/31/2024 03:39 PM
774	Bug	New	High	SARADC0_IN6 1.8V GND 1.3V	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/06/2025 11:14 AM
773	Bug	New	Normal	FD7352S HE-MCS接口	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	12/30/2024 06:36 PM
772	Bug	New	High	WiFi/BT接口	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	KuangJie	12/30/2024 10:44 AM

#	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
771	Bug	New	High	XXXXXXXXXXXXXXXXXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 09:06 PM
770	Bug	New	Normal	ADC_INXXXXXXXXvoltage_rawXXXXXXXX0	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:44 PM
769	Bug	New	Urgent	ADC_INXXXXXXXXXXXX0.1VXXXXXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:46 PM
768	Bug	New	Urgent	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX15mmXX	Ubuntu		XXX	01/03/2025 06:33 PM
767	Bug	New	Normal	XXXXrebootXXXXlogXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/26/2024 04:34 PM
766	Bug	New	High	XXUbuntuXXXXXXXXXX--XXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/26/2024 04:31 PM
765	Bug	New	High	CPUXGPUXNPXXXXXXXXXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 05:48 PM
763	Bug	New	Normal	4kXXXXXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/25/2024 08:18 PM
761	Bug	New	Normal	FD7352S-BSXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 10:28 AM
760	Bug	New	Normal	FD7352S-BS XXXXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/25/2024 06:05 PM
754	Bug	New	High	XXUSB3.0_OTGXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/13/2025 09:53 AM
752	Bug	New	High	FD7352S-BSXXXXAPXXXXXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 10:25 AM
749	Bug	New	High	XXXXXXXXXXXX	Ubuntu		shiliang	12/23/2024 04:05 PM
748	Bug	New	High	rootXXXXXXXXXXXXgst-XXXXXXXXXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	01/10/2025 10:15 AM
747	Bug	New	High	XXXXXXXXXXXXXX4X	Ubuntu		shiliang	12/23/2024 02:34 PM
746	Bug	New	Normal	XXXXXXXXXXXX	Ubuntu		shiliang	12/23/2024 02:27 PM
745	Bug	New	High	XXXXXXXXXXXX	Ubuntu		shiliang	12/23/2024 02:24 PM
743	Bug	New	Urgent	MIPXXXXXXXXXXXX3AXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/31/2024 02:10 PM
742	Bug	New	High	XXXXXXXXXXXXPOPX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:53 PM
739	Bug	New	High	LP11AXXXXX			XXX	12/20/2024 06:19 PM
738	Bug	New	High	LC210XXXXXXXXXXXXXXXXXXXXXXXXXXXXSOCXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	XXX	12/20/2024 04:24 PM
737	Bug	New	High	XXXXXXXX12vXXXXXXXXXXXX24vXXXXXXXXXXXXXXXX X15vX16vXXXXAHDXXXXXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	01/17/2025 03:55 PM
736	Bug	New	High	USB2.0X4GXXXXXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:55 PM
734	Bug	New	High	XXdemoXXXXXXXXXUIXXXX	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:24 PM
733	Bug	New	Normal	XXXXXXXXXXXXXXXXXXXXXXXXXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/31/2024 04:23 PM
731	Bug	New	High	power XXXXXXXXXXXXXXXsystemXXXX	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	01/06/2025 11:18 AM

#	Tracker	Status	Priority	Subject			Assignee	Updated
730	Bug	New	Normal	Recovery	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:44 PM
729	Bug	New	Immediate		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 02:49 PM
728	Bug	New	High	power	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	01/03/2025 06:52 PM
727	Bug	New	Low	system LED	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 03:10 PM
726	Bug	New	High	system LED	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:54 PM
724	Bug	New	Normal					02/17/2025 01:48 PM
721	Bug	New	High		Ubuntu			02/17/2025 01:56 PM
720	Bug	New	Urgent		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 02:59 PM
719	Bug	New	High					02/17/2025 01:56 PM
718	Bug	New	Low	4.77 GB4GB	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/31/2024 02:20 PM
717	Bug	New	High	thermal dmc cpufreq	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/07/2025 02:44 PM
714	Bug	New	High	U050145°C	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	jing	12/16/2024 06:25 PM
713	Bug	New	Urgent	USB/Type-C	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 09:18 PM
712	Bug	New	Normal	J3200 GPIO	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 08:51 PM
711	Bug	New	Normal	MCP2515CAN2&3	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 08:13 PM
710	Bug	New	Urgent	RS485 ttysWK0/ttysWK1	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:55 PM
709	Bug	New	Normal	J3304/J3303 RS485 AB	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:49 PM
707	Bug	New	Normal	J3300 PWM	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 06:02 PM
706	Bug	New	Normal	LED	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 05:57 PM
704	Bug	New	Normal	WIFI/BT	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 04:25 PM
702	Bug	New	Normal	Ethernet	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 03:00 PM
700	Bug	New	Normal	J2500	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	shiliang	03/06/2025 03:20 PM
699	Bug	New	High	J2903--TP	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/06/2025 03:25 PM
695	Bug	New	Normal	MIPI TX/MIPI CSI Rx	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/23/2024 10:30 AM
694	Bug	New	Normal	4Gquectel-CM	Ubuntu	Linux_for_Tegra.tar.gz	Linx	12/13/2024 02:05 PM

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
690	Bug	New	Normal	Mini-PCIE 1808	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/17/2025 11:04 AM
689	Bug	New	Normal	Mini-PCIE	Ubuntu	https://forum.nearidi.com/d/126-hisi3403-xia-zai-gu-jian	shiliang	12/13/2024 10:41 AM
685	Bug	New	High	Master SSD	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 06:53 PM
683	Bug	New	Normal	TX (ETH1)	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 05:45 PM
682	Bug	New	Urgent	LB700--Linuxubuntu	Ubuntu	https://forum.nearidi.com/d/126-hisi3403-xia-zai-gu-jian	sun	12/18/2024 05:36 PM
677	Bug	New	Urgent	LB700--	Ubuntu		sun	03/07/2025 05:25 PM
676	Bug	New	Urgent		Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/23/2024 09:57 AM
675	Bug	New	Normal	MIC/HP GPIO	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 02:42 PM
674	Bug	New	Normal	TF	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/12/2024 01:49 PM
673	Bug	New	High	Onboard EXT SPK	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 11:45 AM
671	Bug	New	Immediate	emmc	Ubuntu	rk3562_lkd210_ubuntu2004.img		01/03/2025 06:57 PM
670	Bug	New	Normal		Ubuntu	Linux_for_Tegra.tar.gz		12/12/2024 11:18 AM
669	Bug	New	High	EHT1	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/23/2024 10:31 AM
668	Bug	New	Normal		Ubuntu	Linux_for_Tegra.tar.gz		12/12/2024 10:22 AM
667	Bug	New	High	60s	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/11/2024 06:02 PM
666	Bug	New	Urgent	EC20 USB3.0 I/O	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/11/2024 04:51 PM
665	Bug	New	High	I/O	Ubuntu	Linux_for_Tegra.tar.gz		12/11/2024 02:39 PM
664	Bug	New	Normal	exfat	Ubuntu	Linux_for_Tegra.tar.gz	Linx	12/11/2024 11:23 AM
663	Bug	New	High	I/O	Ubuntu	Linux_for_Tegra.tar.gz		12/11/2024 11:23 AM
662	Bug	New	High	M.2 SSD	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/11/2024 10:05 AM
659	Bug	New	Normal	AP mcs	Ubuntu	\\192.168.1.250\01-Public\FB101-FD7352\FD7352S-B\update-sdio.img	KuangJie	12/10/2024 05:11 PM
658	Bug	New	Normal		Ubuntu	Linux_for_Tegra.tar.gz	jing	12/10/2024 03:06 PM
657	Bug	New	Normal	RTC	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/10/2024 02:48 PM
656	Bug	New	Normal		Ubuntu	Linux_for_Tegra.tar.gz		12/09/2024 07:33 PM
654	Bug	New	Normal	wifi	Ubuntu	\\192.168.1.250\01-Public\FB101-FD7352\FD7352S-B\update-sdio.img	KuangJie	12/09/2024 03:33 PM

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
653	Bug	New	Normal	FD7352S STA 5G wifi 1	Ubuntu	\\192.168.1.250\01-Public\FB101-FD7352\FD7352S-B\update-sdio.img	KuangJie	12/09/2024 03:00 PM
651	Bug	New	Normal	wifi	Ubuntu		sun	12/05/2024 06:13 PM
650	Bug	New	Normal	Tf U	Ubuntu		sun	12/05/2024 05:25 PM
649	Bug	New	Normal	MCS	Ubuntu		sun	12/05/2024 04:39 PM
648	Bug	New	Normal	LVDS eDP	Ubuntu		sun	12/05/2024 03:52 PM
647	Bug	New	Urgent	HDMI	Ubuntu			02/17/2025 05:29 PM
645	Bug	New	Normal		Ubuntu			02/17/2025 05:33 PM
644	Bug	New	Normal	USB2.0 1A 5V±5%	Debian	LZ210V1.0	mike	12/02/2024 05:51 PM
642	Bug	New	Normal	A/	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	01/14/2025 05:51 PM
639	Bug	New	Urgent	J3300 12V 4.84	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/21/2024 04:20 PM
638	Bug	New	High	4K	Ubuntu	Linux_for_Tegra.tar.gz	Linx	11/21/2024 10:28 AM
637	Bug	New	High	M.2 Slot M3.0	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 04:11 PM
636	Bug	New	Immediate	PCIe3.0 SSD	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 03:53 PM
635	Bug	New	Urgent	HDMI	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	sun	01/15/2025 09:55 AM
634	Bug	New	High	wifi HE-MCS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	KuangJie	11/15/2024 05:26 PM
632	Bug	New	High	BT	Ubuntu	rk3576_lb200_ubuntu2204_12_03.img		02/21/2025 04:01 PM
627	Bug	New	Normal	J2800 USB USB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	11/14/2024 03:19 PM
625	Bug	New	Normal	Type-C	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/04/2024 04:48 PM
624	Bug	New	Normal	Type-C debug	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/04/2024 04:48 PM
623	Bug	New	Urgent	5G	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/09/2024 10:15 AM
620	Bug	New	High		Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	12/06/2024 04:59 PM
619	Bug	New	Normal	J4500/J4501	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	11/13/2024 09:09 PM
615	Bug	New	High	4G	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu		01/17/2025 11:33 AM
609	Bug	New	Urgent	HDMI2 HDMI	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	jing	11/15/2024 04:34 PM
608	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/26/2024 02:32 PM
607	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/08/2024 06:40 PM

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
606	Bug	New	Urgent	XXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	DD	11/08/2024 06:17 PM
605	Bug	New	Normal	0HDMIXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/29/2024 10:09 AM
603	Bug	New	Normal	wifiXXXXXXXXHE-MCS	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	DD	11/08/2024 10:52 AM
601	Bug	New	Normal	USB2.0USB3.0XXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:41 AM
600	Feature	New	Normal	USBXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:55 AM
598	Bug	New	Low	ETH1XXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	DD	11/07/2024 04:07 PM
597	Bug	New	Normal	emmcXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/07/2024 04:07 PM
592	Bug	New	Urgent	rebootXXXXXXXX	Ubuntu	LP11A_Ubuntu18.04_v3.0_20240930_Test.img	DD	11/05/2024 10:28 AM
587	Bug	New	Urgent	16vXXXXAHDXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	04/15/2025 05:03 PM
585	Bug	New	Urgent	HDMIXXXXXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/14/2025 05:50 PM
584	Bug	New	Normal	M.2SSDXXXXXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/15/2025 11:23 AM
583	Bug	New	High	XXXXXX4pin speakerXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	sun	10/30/2024 09:58 AM
582	Bug	New	Normal	XXXXTXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/14/2025 06:30 PM
581	Bug	New	Urgent	AHDXXXXXXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu		11/01/2024 10:10 AM
580	Bug	New	Normal	XXXXXXXX			DD	10/30/2024 04:49 PM
579	Bug	New	Normal	PCBAXXXX		/	DD	10/30/2024 04:48 PM
576	Feature	New	Urgent	FPGAXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	01/17/2025 02:06 PM
570	Bug	New	High	macXXXXXXXXmacXXXXXIPXXXX	Ubuntu	rk3399pro_KZ117_ubuntu_gaussion_ddr3_20240628.img	Linx	11/25/2024 03:32 PM
565	Bug	New	Urgent	XXXXXXXXUSB	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	sun	10/29/2024 09:36 AM
562	Bug	New	Normal	wifi_pingwalnXXXXpingwifiiP	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img	KuangJie	09/23/2024 11:30 AM
556	Bug	New	Urgent	FD7352S,STA5G/2.4GXXXXXXXXXXXX mcsXXXX	Ubuntu	update-sdio.img	KuangJie	09/14/2024 02:28 PM
555	Bug	New	Urgent	FD7352S/PXXXXAPXXXXXXXXXXXXAPXXXX XXXXAPXXXXXXXXSSID 1XXXX 2XXXXXXXXSSID	Ubuntu	update-sdio.img	KuangJie	12/18/2024 07:30 PM
553	Bug	New	High	FD7352PSTA2.4GXXXXax-40XXXXtxmcs 11 mcs11XXXXXXXXXXXXmcsXXXX	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:45 PM
552	Bug	New	High	FD7352PSTAXXXXac-80XXXXXiperf3XXXXXXXX XXXXXXXX	Ubuntu	update-pcie.img	KuangJie	09/12/2024 10:31 AM

#	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
551	Bug	New	High	AP6275S LPA3588 AP 70%	Ubuntu	update.img	sun	09/11/2024 06:42 PM
550	Bug	New	High	FD7352P, STA 2.4G n only rx ac.	Ubuntu	update-pcie.img	KuangJie	09/10/2024 04:59 PM
549	Bug	New	High	FD7352P, ax80 tx 70.	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:48 PM
546	Bug	New	Normal	TF U	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/05/2024 03:17 PM
543	Bug	New	Immediate		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		01/17/2025 02:00 PM
535	Feature	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	10/23/2024 04:31 PM
525	Bug	New	Normal	ESD -8KV 485/gpio		-	er	10/30/2024 04:44 PM
517	Bug	New	High	X_Y	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img		08/13/2024 03:14 PM
514	Bug	New	Normal					08/27/2024 10:22 AM
508	Bug	New	Normal		Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	KuangJie	08/07/2024 10:40 AM
500	Bug	New	High	SIM	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img		07/24/2024 11:50 AM
496	Bug	New	Normal	gpio	Ubuntu	lkd3588-t0-ubuntu-240718.img	sun	07/22/2024 11:30 AM
494	Feature	New	Low	-20 AHD KP11A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.2	Linx	11/07/2024 02:05 PM
492	Bug	New	High	KD17A, iperf3 100 Mbits/sec . 500-600Mbits/sec	Ubuntu	KZ17A_ubuntu20.04_v1.9_fixed_fd7352s_crash_20240708.img	sun	07/17/2024 02:16 PM
489	Bug	New	Urgent	sdio	Ubuntu	KZ17A_ubuntu20.04_v1.8_yt8521_driver_strength_20240704.img	jing	07/16/2024 11:05 AM
486	Bug	New	Normal	LKD3588_Debian_U	Debian		Linx	07/15/2024 07:06 PM
483	Bug	New	Normal		Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 06:09 PM
482	Bug	New	High	LVDS LD166 LVDS	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:08 PM
481	Bug	New	Normal	bt	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:08 PM
480	Bug	New	Normal	wifi	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:07 PM
476	Bug	New	High	USB1 3.0 2.0 3.0	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	shiliang	07/08/2024 06:18 PM
472	Bug	New	High	12V OUT 11.2V	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-v1.0.img	jing	07/01/2024 04:26 PM
471	Bug	New	Urgent	linux T	Ubuntu	update.img		07/12/2024 10:18 AM
464	Bug	New	High	M.2	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\pcie3.0\LKD3588_ubuntu20.04_v1.0_20240523_1544.img	sun	06/14/2024 02:33 PM
439	Bug	New	High	LB120 eth1 350	Ubuntu	LBA3568_ubuntu20.04_v1.0_20240301_2020.img	Linx	03/29/2024 10:58 AM
438	Bug	New	Normal	LCM		-	shiliang	03/18/2024 05:02 PM
436	Bug	New	Normal	APP	Android	PX30_Test_V01_20240308.img		03/12/2024 05:57 PM

#	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
435	Bug	New	High	KB17A cannot connect to AP with SSID, cannot connect to WiFi	Ubuntu	update.img	sun	03/12/2024 03:11 PM
434	Bug	New	Urgent	5G (RM500U-CNV) cannot connect	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230801_1621.img	Linx	09/25/2024 04:23 PM
433	Bug	New	Normal	KB19B cannot connect to AP		-	jing	11/14/2023 09:28 PM
432	Bug	New	Normal	CAN loopback cannot connect	Ubuntu		sun	11/08/2023 05:37 PM
426	Bug	New	Normal	lanuch cannot boot	Android	update-android-v8.0.3-20231019.img	sun	10/20/2023 02:19 PM
425	Bug	New	Normal	APP Stopping	Android	update-android-v8.0.1.img	jing	10/19/2023 07:15 PM
424	Bug	New	Normal	Power ON/OFF NG	Android	update-android-v8.0.1.img	sun	10/19/2023 07:11 PM
423	Bug	New	Normal	recovery	Android	update-android-v8.0.1.img	jing	10/19/2023 07:05 PM
422	Bug	New	Normal	ADB	Android	update-android-v8.0.1.img	jing	10/20/2023 12:53 PM
420	Bug	New	Urgent	LPA3588 HDMI12H cannot connect	Ubuntu		sun	10/17/2023 09:49 AM
419	Bug	New	Urgent	3588 cannot boot 40-50ms cannot boot 100ms	Ubuntu		Linx	10/16/2023 11:27 AM
418	Bug	New	Urgent	LPA3588 cannot boot	Ubuntu		sun	10/16/2023 11:23 AM
410	Bug	New	Urgent	HDMI3 cannot connect	Ubuntu	LZ160XXX03_RL_AC_F1_230914A-3588-Android12.img	sun	09/21/2023 11:45 AM
408	Bug	New	High	cannot boot sony1.mp4 ch-test.wav	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 11:49 AM
407	Bug	New	High	HDMI_OUT3 cannot connect	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 10:06 AM
406	Bug	New	High	cannot boot sony1.mp4 ch-test.wav	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 05:46 PM
388	Feature	New	High	cannot boot 3588 cannot boot	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/26/2023 02:44 PM
380	Bug	New	High	RS232 COM3 cannot connect ttyWK3	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/10/2023 11:57 AM
376	Bug	New	Normal	/rockchip-test/np2 rknn_demo.sh npu_freq_scaling.sh	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 04:02 PM
372	Bug	New	High	HDMI-RX cannot video1	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/04/2023 11:49 AM
370	Bug	New	Normal	USB cannot type-c USB	Android	LZ160_3588_Android12_v1.0_20230629.img	sun	07/03/2023 03:42 PM
367	Bug	New	Normal	SD cannot boot SD	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM
366	Bug	New	Normal	UnixBench GImark2-es2 Stream	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 03:26 PM
365	Bug	New	Normal	A/INI1 234 cannot boot 50mV	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM
354	Bug	New	Normal	LB170, cannot M.2	Ubuntu	lb170_3588_ubuntu20.04_v1.0_20230607_1025.img	sun	06/27/2023 10:51 AM
348	Bug	New	Normal	LVDS	Ubuntu	Factory_Image		07/11/2023 03:22 PM
342	Bug	New	Normal	usb3.0 3.0U	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/03/2023 11:33 AM
339	Bug	New	Normal		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/18/2023 04:25 PM
338	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/14/2023 10:35 AM

#	Tracker	Status	Priority	Subject	OS	Log File	Assignee	Updated
337	Bug	New	High	Audio output issue	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/18/2023 04:22 PM
334	Bug	New	Normal	HDMI-OUT3 audio output issue	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 06:16 PM
331	Bug	New	Normal	A/I IN1 IN2 IN3 IN4 audio output issue 50mV	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 03:31 PM
330	Bug	New	Normal	Connection Failed Protocol not available.	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:49 PM
329	Bug	New	Normal	Audio output issue pop	Ubuntu	RK3588_UBUNTU_V1_230519.img	sun	06/09/2023 05:49 PM
328	Bug	New	Normal	Audio output issue POP	Ubuntu	RK3588_UBUNTU_V1_230519.img	sun	06/09/2023 05:47 PM
327	Bug	New	Normal	Audio output issue "mpv Media Player" 8k.mp4	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:57 PM
326	Bug	New	Normal	Audio output issue "mpv Media Player" jellyfish-140-mbps-4k-uhd-hevc-10bit.mkv	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:58 PM
323	Bug	New	Normal	2.0 3.0 USB output ext4 audio output issue	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:29 PM
319	Bug	New	High	4 COM RS232 audio output issue	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/18/2023 03:40 PM
316	Bug	New	Normal	LPA3588_Ubuntu 20.04.5_HDMI OUT3 audio output issue	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 10:14 AM
311	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 M.2 ext4 audio output issue	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 03:44 PM
310	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 A/I IN1 IN2 IN3 IN4 audio output issue 50mV	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/12/2023 04:45 PM
309	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 A/I IN1 IN2 IN3 IN4 audio output issue, adc4 adc5 adc6 adc7	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/12/2023 04:42 PM
308	Bug	New	Normal	USB3.0 HUB USB3.0 Device	Ubuntu	LZ11200001_FT_GB_BASE_230526A.img		05/26/2023 10:45 PM
305	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 BT audio output issue	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	01/14/2025 06:32 PM
300	Bug	New	Normal	Audio output issue	Ubuntu	KZ11A664_RL_LB_BASE_V01_20230505.img	shiliang	05/22/2023 08:44 PM
291	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 audio output issue pop	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 04:45 PM
288	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 audio output issue	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 04:36 PM
286	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 audio output issue 4k 8K	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	Linx	06/06/2023 11:39 AM
284	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 DP audio output issue	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 04:08 PM
283	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 HDMI audio output issue	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 03:43 PM

#	Tracker	Status	Priority	Subject			Assign ee	Updated
282	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 HDMI _HDMI--OUT3	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 03:35 PM
280	Bug	New	Normal		Ubuntu	update_add_hosts_changelog.img	Linx	05/17/2023 07:54 PM