

LP11A - Issues

#	Tracker	Status	Priority	Subject	OS	Hardware	Assignee	Updated
644	Bug	New	Normal	USB2.0 port 1A port cannot supply 5V±5%	Debian	LZ210V1.0	mike	12/02/2024 05:51 PM