

KP12C - Issues

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
796	Bug	New	Normal	usb2.0→usb3.0 hub 30%↓	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	Linx	01/14/2025 11:54 AM
795	Bug	New	Normal	AHD	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/13/2025 09:55 AM