

LB160 - Issues

#	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
994	Bug	New	High	TF	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:29 PM
993	Bug	New	High	4G	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:15 PM
992	Bug	New	High	4GModem hangup	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:08 PM
990	Bug	New	High	J4500/J4501	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 11:56 AM
989	Bug	New	High	GPIO	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:31 PM
988	Bug	New	High	RTC	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	jing	06/20/2025 10:06 AM
987	Bug	New	High	6demo	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 06:00 PM
986	Bug	New	High	sta sys	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 05:35 PM
985	Bug	New	High	eth1, 10M	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 04:48 PM
984	Bug	New	High	etho	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	jing	06/19/2025 04:40 PM
983	Bug	New	High	5V0 3V3	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 04:03 PM
981	Bug	New	High	485	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 03:06 PM
980	Bug	New	High	USB3.0 3.0 2.0	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 11:49 AM
979	Bug	New	High	PWR	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 10:45 AM
978	Bug	New	High		Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	jing	06/19/2025 10:37 AM