

LB200 - Issues

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
852	Bug	New	Urgent	type-c		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img		02/28/2025 11:25 AM
845	Bug	New	High	USB3.0 HUB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/27/2025 03:25 PM
840	Bug	New	Normal	mmcbld0 mmcbld1	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/18/2025 05:20 PM
837	Bug	New	Urgent	USB3.0 3.0U		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	yunca	02/18/2025 02:23 PM
836	Bug	New	Normal	U		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/17/2025 03:31 PM
724	Bug	New	Normal					02/17/2025 01:48 PM
721	Bug	New	High		Ubuntu			02/17/2025 01:56 PM
719	Bug	New	High					02/17/2025 01:56 PM
632	Bug	New	High	BT	Ubuntu	rk3576_lb200_ubuntu2204_12_03.img		02/21/2025 04:01 PM
627	Bug	New	Normal	J2800 USB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu204_11_11.img	er	11/14/2024 03:19 PM
625	Bug	New	Normal	Type-C	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu204_11_11.img	er	12/04/2024 04:48 PM
624	Bug	New	Normal	Type-C debug	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu204_11_11.img	er	12/04/2024 04:48 PM
623	Bug	New	Urgent	5G	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu204_11_11.img	er	12/09/2024 10:15 AM
620	Bug	New	High		Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	12/06/2024 04:59 PM
619	Bug	New	Normal	J4500/J4501	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	11/13/2024 09:09 PM