

LB200 - Issues

#	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
632	Bug	New	High	BT module	Ubuntu	rk3576_lb200_ubuntu2204_12_03.img	er	02/21/2025 04:01 PM
627	Bug	New	Normal	J2800 USB module not working	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	11/14/2024 03:19 PM
625	Bug	New	Normal	Type-C module not working	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/04/2024 04:48 PM
624	Bug	New	Normal	Type-C debug module not working	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/04/2024 04:48 PM
623	Bug	New	Urgent	5G module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/09/2024 10:15 AM
620	Bug	New	High	WiFi module	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	12/06/2024 04:59 PM
619	Bug	New	Normal	J4500/J4501 module	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	11/13/2024 09:09 PM