

LP112 - Issues

#	Tracker	Status	Priority	Subject	OS	Issue ID	Assignee	Updated
776	Bug	New	High	USB2.0 to USB1.0 adapter	Ubuntu	LZ112_3588_ubuntu20.04_v1.0_20240204_1649		01/02/2025 02:05 PM
342	Bug	New	Normal	usb3.0 to 3.0U	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/03/2023 11:33 AM
339	Bug	New	Normal		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/18/2023 04:25 PM
338	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/14/2023 10:35 AM
337	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/18/2023 04:22 PM
308	Bug	New	Normal	USB3.0 HUB to USB3.0 Device	Ubuntu	LZ11200001_FT_GB_BASE_230526A.img		05/26/2023 10:45 PM
280	Bug	New	Normal		Ubuntu	update_add_hosts_changelog.img	Linx	05/17/2023 07:54 PM