

LP122 - Issues

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
635	Bug	New	Urgent	HDMI不工作	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	sun	01/15/2025 09:55 AM
634	Bug	New	High	wifi不工作HE-MCS不工作	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu		11/15/2024 05:26 PM
615	Bug	New	High	4G不工作	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu		01/17/2025 11:33 AM
609	Bug	New	Urgent	HDMI2不工作HDMI不工作	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	jing	11/15/2024 04:34 PM
565	Bug	New	Urgent	USB不工作	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	sun	10/29/2024 09:36 AM
434	Bug	New	Urgent	5G(RM500U-CNV)不工作	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230801_1621.img	Linx	09/25/2024 04:23 PM
380	Bug	New	High	RS232不工作--COM3不工作ttySWK3不工作	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/10/2023 11:57 AM
376	Bug	New	Normal	/rockchip-test/npu2rknn_demo.sh\npufreq_scaling.sh不工作	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 04:02 PM
372	Bug	New	High	HDMI-RX不工作video1	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/04/2023 11:49 AM
367	Bug	New	Normal	SD不工作SD不工作	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM
366	Bug	New	Normal	UnixBench\nGImark2-es2\nStream不工作	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 03:26 PM
365	Bug	New	Normal	A/1\nINI1\n2\n3\n4\n5\n6\n7\n8\n9\n10\n11\n12\n13\n14\n15\n16\n17\n18\n19\n20\n21\n22\n23\n24\n25\n26\n27\n28\n29\n30\n31\n32\n33\n34\n35\n36\n37\n38\n39\n40\n41\n42\n43\n44\n45\n46\n47\n48\n49\n50\n51\n52\n53\n54\n55\n56\n57\n58\n59\n60\n61\n62\n63\n64\n65\n66\n67\n68\n69\n70\n71\n72\n73\n74\n75\n76\n77\n78\n79\n80\n81\n82\n83\n84\n85\n86\n87\n88\n89\n90\n91\n92\n93\n94\n95\n96\n97\n98\n99	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM