

LPM3568 - Issues

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
601	Bug	New	Normal	USB2.0 to USB3.0 adapter	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:41 AM
600	Feature	New	Normal	USB to USB adapter	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:55 AM
598	Bug	New	Low	ETH1 interface	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/07/2024 04:07 PM
597	Bug	New	Normal	emmc storage	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/07/2024 04:07 PM