

LPM3568 - Issues

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
775	Bug	New	Normal	ETH0 config ifconfig	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	12/31/2024 03:39 PM
608	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/26/2024 02:32 PM
607	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/08/2024 06:40 PM
606	Bug	New	Urgent		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/08/2024 06:17 PM
605	Bug	New	Normal	HDMI	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/29/2024 10:09 AM
603	Bug	New	Normal	wifi HE-MCS	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/08/2024 10:52 AM
601	Bug	New	Normal	USB2.0 USB3.0	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:41 AM
600	Feature	New	Normal	USB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:55 AM
598	Bug	New	Low	ETH1	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/07/2024 04:07 PM
597	Bug	New	Normal	emmc	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/07/2024 04:07 PM